

Bluetooth Device Setting Guide

for Windows Platform

Revision 1.2

December 2014




Precautions


- This program assumes serial port connection or USB connection.
- Serial port connection printer
 - If user computer has only USB port, USB-Serial convert cable is required. Installing dedicated driver could be needed with the type of USB-Serial converter. USB-Serial converter cable is not included in the standard accessory set.
 - When printer communicates with setting program, the baud rate of the setting program should be same as the one of the printer. If the baud rate is unclear, it can be checked on the self-test. To print self-test, turn on the power of the printer while holding down <FEED> button
- USB connection printer
 - Separate drivers or software are not required to be installed, and printer device is automatically detected after connecting the printer to PC with USB cable.
 - No need to set baud rate.
- VCP USB connection printer
 - Some printer which has USB port may need a VCP driver. It uses USB port and cable but works internally same as serial connection.
If a VCP driver should be installed, refer to "VCP Driver Installation Guide".

- 1) Turn on the power of a printer and connect a cable between a printer and a computer.
- 2) Execute the program and select the port which is connected to the printer, and click <Open> button.


<Serial>




<USB>



- 3) Click the <Get Info> button and bring the Bluetooth information of the printer.
Each of the Bluetooth Device Address, Pinkey, and Bluetooth Device Name are indicated.



- 4) Click the checkbox in "Pinkey Setting" category.
Input new Pinkey value and click the <Set Pinkey> button.
Only number is available to input and maximum size of number is 16.



- 5) Click the checkbox in "Bluetooth Device Name" category.

Input new device name to "Set BDN" and click the <Set BDN> button.

Only English character, number, symbol (-, _ , ~, null) are available to input and maximum size of number is 29.

WS_BT_Setting_Utility Ver2.2

Communication setting

Serial USB

Port: COM1 Baud Rate: 57600 Parity: None Data Bits: 8 Stop Bit: 1

Status: Success Open Close

Bluetooth Device Address

Current BDA: 00150EE18FD1 Get Info

Pinkey Setting

Current PinKey: 0000

Set PinKey: Set Pinkey

Bluetooth Device Name

Current BDN: WOOSIM5

Set BDN: WOOSIM2 Set BDN